
## **Smoke and Dye Testing Summary**

## **High Level Sewershed**

Run Summa	iry <del> </del>						_
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-181	Smoke	7/21/2009	ADS/TM	S15AA_041MH	Dry	Yes	204.58



## **Smoke and Dye Testing Summary**

## **High Level Sewershed**

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-181	Smoke	7/21/2009	ADS/TM	S15AA_041MH	Dry	Yes	204.58

lated Pipes ————————————————————————————————————						
	Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)	
	S15AA_014G1	S15AA_014MH	S15AA_024MH	14.6114	8	
	S15AA_024G1	S15AA_024MH	S15AA_002MH	42.9664	8	
	S15AA_002G1	S15AA_002MH	S15AA_036MH	52.1745	8	
	S15AA_036G1	S15AA_036MH	S15AA_012MH	26.9834	8	
	S15AA_041G1	S15AA_041MH	S15AA_036MH	67.8403	8	
_						

**Observations & Photos**